

Contents

BINDER 1	
United States I	Environmental Protection Agency
	s Superfund Site
Releasable Do	cuments as of 16-Oct-2006
Special Collect	tion 18070
-	ovember 2006
Libby. Montan	a Asbestos Project
Property Infor	,
Mel and Lerah	
Former Screen	ing Plant
5000 Highway	
	Photos
	1999
	2000
	2001
	2002
	2003
	Scanned 35 mm photos
	Rainy Creek Photos 2000 - 2002
CD 2 -	Photos
	2004
	2005
CD 3 -	Photos
	2006
CD 4 -	Scanned Documents from:
	Property Appraisal
	Archaeological Survey
	Correspondence between EPA, Volpe, CDM, and Parkers
	Fill Material Information
	Investigation Information
	Notes and Emails from EPA, Volpe, and CDM
	Rip Rap Information
	Sample Results
	Settlement Information
	Stipend Information
	Workplans



CD 5 - Scanned Documents from: Logbooks Property Completion Checklists Removal Information

Restoration Information

Septic System

Contractor Submittals

Drawings

Screening Plant Record Drawings
Screening Plant Record Drawings
Record Site Plan
Site Restoration Details
Site Restoration Details
Record Electrical Site Plan E-1
Electrical Details E-2
Irrigation System Layout May 6, 2005
Notes from April 12, 2004 Site Inspection - North
Notes from April 12, 2004 Site Inspection - South
Surface Drainage Improvements
Surface Drainage Improvements
Parker Property - Mine Side of Highway 37
Soil, Boulder, and Haul Road Removal
Grading Plan
Erosion Control Details
Septic System
House 1 Septic System1
House 2 Septic System
2003 Site Restoration Plan - North
2003 Site Restoration Plan – South
Screening Plant Restoration March 2003 (work to be completed in 2003)
Screening Plant Restoration March 2003 (work to be completed in 2003) Title Page
2003 Site Restoration Plan - North
2003 Site Restoration Plan - South
2003 Site Restoration Plan Details
2003 Site Restoration Plan Details



2003 Site Restoration Plan Details	
Electrical Site Plan	E-1
Electrical Details	E-2
BINDER 2	
Screening Plant Asbestos Removal Project (Signed by Parkers on 05-1	16-02)
Screening Plant Asbestos Removal Project (Signed by Farkers on 65-2)	•
Site Restoration Plan - North	
Site Restoration Plan - South	
Site Restoration Plan Details.	
Site Restoration Plan Details.	
Rainy Creek Fishing Dock Details	
Rainy Creek Fishing Dock Details Revised per Agreement between Gov	
Owner	
Electrical Site Plan	
Electrical Details	
Screening Plant Test Pit Sampling Plan	Sheet 1 of 2
Screening Plant Test Pit Sampling Plan	
Interim Erosion Control Plan - North	
Interim Erosion Control Plan - South	
Interim Erosion Control Plan Details	
Screening Plant - North Approximate Locations of Archeological Trenc	h and Pit
Excavations and Soil Removal Test Pits dated 10/9/00	
Screening Plant - South Approximate Locations of Archeological Trench	h and Pit
Excavations and Soil Removal Test Pits dated 10/6/00	
Screening Plant Asbestos Removal Project August 2000	
Screening Plant Asbestos Removal Project August 2000 Screening Plant Asbestos Removal Project	Title Page
Existing Conditions Plan - North	-
Existing Conditions Plan - South	
Erosion Control Plan - North	
Erosion Control Plan - South	
Demolition Plan - North	
Demolition Plan - South	
Final Grading Plan - North	
Final Grading Plan - South	
Test Pits and Air Monitoring Locations - North	
Test Pits and Air Monitoring Locations - South	
165t 1 to and 1 in monatoring Locations - Journ	C-10
MARCOR Drawing Submittal	
Dismantling / Demolition	Sheet 1 of 2
· · · · · · · · · · · · · · · · · · ·	



Table of Contents Parker Property Information

Dismantling / Demolition	Sheet 2 of 2
Earthwork/Excavation	
Earthwork/Excavation	
Erosion Control	
Erosion Control	Sheet 2 of 2
Temporary Facilities	Sheet 1 of 2
Temporary Facilities	



Libby, Montana
Asbestos Project
Property Information
for
Mel and Lerah Parker
Former Screening Plant
5000 Highway 37 N
Libby, Montana
BINDER 2 of 2

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1073566

SITE NAME:	LIBBY ASBESTOS
DOCUMENT DATE	: 11/17/2006
Due to one of the fo	DOCUMENT NOT SCANNED collowing reasons:
☐ PHOTOGRAPHS	3
☐ 3-DIMENSIONA	L
☑ OVERSIZED	
☐ AUDIO/VISUAL	
☐ PERMANENTLY	BOUND DOCUMENTS
☐ POOR LEGIBILI	TY
□ OTHER	
☐ NOT AVAILABL	E
	UMENTS NOT TO BE SCANNED , Data Validation, Sampling Data, CBI, Chain of Custody)
DOCUMENT DESC	RIPTION:
SEE TABLE OF	CONTENTS (TOC)